



State of Utah

Department of Natural Resources

ROBERT L. MORGAN
Executive Director

Division of
Oil, Gas & Mining

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

June 24, 2004

TO: Minerals File
FROM: Tom Munson, Senior Reclamation Hydrologist 
SUBJECT: Site Inspection, Brush Resources, Inc., Hogsback, M/023/053, Juab County, Utah

Date of Inspection: May 3, 2004
Time of Inspection: 1:00 – 1:30 p.m.
Conditions:
Participants: Tom Munson - DOGM

Purpose of Inspection: To view and evaluate the success of the seeding results done in the Fall of 2003, per operator request to close site and release bond.


Observations:

I observed multiple species of plants, grasses and shrubs germinating from last fall's reclamation. It appears that it should do well, given the fact if we continue to get some moisture. The overall reclamation looked good.

Conclusions and Recommendations:

It is recommended that the Division release a portion of the reclamation bond that covers regrading work. We should retain enough monies to cover reseeding work if necessary for revegetation success.

TM:jb
O:\M023-Juab\M0230053-Hogsback-brush\inspections\insp-hb-05032004.doc



HOGSBACK - Recontouring work (North end project area)

PANORAM3.JPG



HOGSBACK - recontoured surface (North end looking south)

PANORAM4.JPG



HOGSBACK RECLAMATION WORK (PRE-2003)
(View looking SOUTH)

PANORAM5.JPG



HOGSBACK Reclamation - Northern area
(View looking West)* composted manure
being ripped into soil

PANORAM6.JPG



11.18.2003 16:42

HOGSBACK Reclamation work (ripping composted
(View to ENE) manure into regraded)
area

PANORAM1.JPG



11.18.2003 16:47

HOGSBACK reclamation work (North end disturbed area)
(View looking WSW)

PANORAM2.JPG



DSCN0740.JPG 2003/11/18 17:09:41

Rock Check Dam - Sediment control
(west side of access road)



DSCN0741.JPG 2003/11/18 17:10:58

Older exploration trench
(to be backfilled)

unloading Sheepfoot
imprinter



DSCN0714.JPG 2003/11/18 16:23:29



DSCN0718.JPG 2003/11/18 16:38:53



DSCN0720.JPG 2003/11/18 16:42:46



Ripped compost
ready for seed'.

Sheepfoot roller



DSCN0717.JPG 2003/11/18 16:28:37

Loading compost manure



DSCN0719.JPG 2003/11/18 16:41:06

Ripping compost
into surface



DSCN0721.JPG 2003/11/18 16:42:55


Loading compost



DSCN0722.JPG 2003/11/18 16:43:05

DSCN0723.JPG 2003/11/18 16:43:15

Recontoured compost
& rippled (eastern edge)



DSCN0726.JPG 2003/11/18 16:48:13

Contoured area
View to the south



DSCN0730.JPG 2003/11/18 16:51:52

Recontoured area
(view to North)



DSCN0737.JPG 2003/11/18 17:07:03

Spreading compost



DSCN0739.JPG 2003/11/18 17:07:22

Ripping compost into
Ripped compost seed



DSCN0727.JPG 2003/11/18 16:48:28

Ripping in compost



DSCN0733.JPG 2003/11/18 16:53:07



DSCN0738.JPG 2003/11/18 17:07:13



DSCN0740.JPG 2003/11/18 17:09:41



DSCN0741.JPG 2003/11/18 17:10:58



PANORAM1.JPG



PANORAM2.JPG



PANORAM3.JPG



PANORAM4.JPG



PANORAM5.JPG



PANORAM6.JPG